

Invoice Summary Sheet – Matt Smith (Dormers)

Cost for Trim Above Dormers, Option 2	Cost	Quantity	Subtotal	Vat %	Vat	Total
Large Epxoy Resin Repairs LHS & MIDDLE LEFT Dormers	£290.00	2	£580.00	20.00%	£116.00	£696.00
Replace Rotten Sides and Front RHS & MIDDLE RIGHT Dormers	£640.00	2	£1,280.00	20.00%	£256.00	£1,536.00
Timber: 8 metres of Large, Quadrant, and 2-part Sections	£771.10	1	£771.10	20.00%	£154.22	£925.32
*would be wise to have a roofer check lead flashing is properly sealed after repairs						
					Window Total	£3,157.32